



# D0 Status Report 11/28/2005

Taka Yasuda Fermilab



# Data Taking for 11/14 - 11/20



| Day         | Delivered             | Recorded              | Eff. | Comments   |
|-------------|-----------------------|-----------------------|------|--|
| 11/21 (Mon) | 2.53 pb <sup>-1</sup> | 2.19 pb <sup>-1</sup> | 86 % | Store 4515 lost.   |
| 11/22 (Tue) | 0 pb <sup>-1</sup>    | 0 pb <sup>-1</sup>    |      |  |
| 11/23 (Wed) | 0 pb <sup>-1</sup>    | 0 pb <sup>-1</sup>    |      | A broken MDT wire repaired. Starting a test to see if it holds.          |
| 11/24 (Thu) | 0 pb <sup>-1</sup>    | 0 pb <sup>-1</sup>    |      | Happy Thanksgiving.  |
| 11/25 (Fri) | 0 pb <sup>-1</sup>    | 0 pb <sup>-1</sup>    |      | Lost cooling water due to ice blocking the pond water inlet. Fire alarm. |
| 11/26 (Sat) | 0 pb <sup>-1</sup>    | 0 pb <sup>-1</sup>    |      | MDT wire test completed.   |
| 11/27 (Sun) | 0 pb <sup>-1</sup>    | 0 pb <sup>-1</sup>    |      |  |

| i            |                       | ı                     |       |  |
|--------------|-----------------------|-----------------------|-------|--|
| 11/21-11/272 | 2.53 pb <sup>-1</sup> | 2.19 pb <sup>-1</sup> | 86 %  |  |
| 11,2111,272  | 2.33 pb               | 2.13 pb               | 00 /0 |  |
|              |                       |                       |       |  |



#### **Notable Events**



- 11/21 (Mon)
  - 40 min downtime due to Muon readout problems.
  - Store 4515 lost due to quench.
    - BLM dose was 35 rad/sec.
    - There is no apparent damage to SMT.
  - Started taking cosmic muon runs.
- 11/22 (Tue)
  - Supervised access began.
    - Muon system surveyed.
    - North EF iron opened.
    - PDT Front-end boards replaced.
- 11/23 (Wed)
  - Supervised access continues.
    - North A-layer pixels opened.
    - A broken MDT wire repaired.



## **Notable Events**



- 11/24 (Thu)
  - Lost cooling water due to ice blocking the pond water inlet.
- 11/25 (Fri)
  - Painful recovery from the loss of cooling water earlier.



### Short Shutdown Plan



- Repair a broken wire in a MDT plane.
  - Requires opening the North EF iron and the North A-layer pixels.
  - Total time to prepare for this work, including survey, is 14 hours.
  - Total time to close the EF is 4 hours.
- Repair Calorimeter preamp power supplies and investigate ICD pulser problems.
  - Requires opening the cathedral.
  - Opening the cathedral takes 4 hours.
  - Closing the cathedral and survey planned for 12/5 (Mon).
- Test Run 2b Muon PDT Control Boards.
- Maintenance work on HVAC UPS.
- Repair L1 Cal water leak.
- Take cosmic muon events.